

TECHNICAL BULLETIN

The 9th edition FireNET Plus panel was tested and listed as compatible with firmware version 07.0027 as per UL864 9th edition standards.

Firmware Version 07.0027 addresses the following:

- ✓ SOM initialization failure when the SOM is programmed to be used on a Cause & Effect through the Loop Explorer.
- ✓ Add and Delete feature for the built-in dialer versions of the panel.
- ✓ Enhanced performance with the phone line supervision and reporting on the built-in dialer versions of the panel.
- ✓ Enhanced FNP-LED (Graphix Display Panel) performance and supervision.

Underwriters Laboratories does allow the flashing of panel firmware in the field as UL864 9th edition requirements.

Please contact Technical support to obtain a copy of the Firmware version 07.0027 and a new enhanced version of the Loop Explorer 6.1014 that supports FireNET, FireNET Plus and Network Annunciator.

If you have any questions regarding this matter please contact Technical Support.

Technical Support
1-800-845-6692
Technicalsupport@hochiki.com

Initial Release: 05/28/2010
TB-003
Rev. 1.00