

## TECHNICAL BULLETIN

The 9<sup>th</sup> edition FireNET panel and Network Annunciator (FN-LCD-N) were tested and listed as compatible with firmware version 4.00 as per UL864 9<sup>th</sup> edition standards.

Firmware Version 4.00 or greater is required for compatibility with the new products: FRCMA, FRCMA-I, R2ML, R2ML-I, R2MH, R2MH-I, ALK-V, ACA-EA, SOM-A, SOM-AI, FireNET Plus panel networking.

Firmware Version 4.00 also addresses the following:

- ✓ Duplicate troubles generated for AC loss when Reset is pressed while the AC is disconnected.
- ✓ SOM initialization failure if the Panel holds more than 75 ASB's
- ✓ Enhanced performance with the FN-DAC phone line supervision.
- ✓ Enhanced Serial Annunciator performance and supervision.

Underwriters Laboratories does allow the flashing of panel firmware in the field as UL864 9<sup>th</sup> edition requirements.

Please contact Technical support to obtain a copy of the Firmware version 4.00.

If you have any questions regarding this matter please contact Technical Support.

Technical Support  
1-800-845-6692  
[Technicalsupport@hochiki.com](mailto:Technicalsupport@hochiki.com)

Initial Release: 11/19/09  
TB-001  
Rev. 1.00