



Hochiki America Corporation
7051 Village Drive, Suite 100
Buena Park, CA 90621-2268
Phone (714) 522-2246
Fax (714) 522-2268

December 7, 2020

SLV-24V, SLV-24N, and SOC24-V, SOC-24VN Sensors,

To Whom It May Concern:

Please be advised, the SLV-24V, SLV-24N and SLV-24M are obsolete.
Both the SLV-24V and the SLV-24N have been replaced by the SOC-24V and SOC-24VN

Obsolete	Replacement
SLV-24V	SOC-24V
SLV-24N	SOC-24VN
SLV-24M	No Replacement

If you have any questions regarding this letter, please contact International Sales at 714-670-3235.
Thank you for your understanding.

Sincerely,

Jonathan Keener
Marketing Manager
Hochiki America Corporation